


VALVE ASSY
 SCHNELLOESEVENTIL KPL
 VALVE DESSER RAPIDE CPL

997-084-58339

Figure
 Bild
 Figure

8458339

1614-05



Item Pos. Réf	Part No. Teil-Nr. Pièce No	Designation Benennung Désignation	all alle tous	Qty/assy Stck/Variante Pièce/ensemble								Figure Bild Figure	
				A	B	C	D	E	F	G	H		
1	997-084-58339	VALVE ASSY SCHNELLOESEVENTIL KPL VALVE DESSER RAPIDE CPL	1										
2		COVER NO SPARE PART DECKEL KEIN ERSATZTEIL COUVERCLE AUCUNE PIECE DE RECH	1										
3	997-084-61448	SEALING RING DICHTRING ANNEAU D ETANCHEITE	1										
4	997-0730-3697	PLUG STOPFEN BOUCHON	1										
5	997-014-09025	DIAPHRAGM MEMBRAN DIAPHRAGME	1										
6		HOUSING NO SPARE PART GEHAEUSE KEIN ERSATZTEIL BOITIER AUCUNE PIECE DE RECHANGE	1										
7	997-007-66480	FILL-HEAD SCREW M6X16 LINSENSCHRAUBE VIS A TETE BOMBEE	1										
8	997-084-63205	BREATHER VALVE ASSY ENTLUEFTUNGSVENTIL FR SOUPEPE D AERATION	1										
10	997-009-18826	RETAINING RING 24X1,2 SICHERUNGSRING CIRCLIP	1										
11	997-084-74960	REPAIR KIT REPARATURSATZ LOT DE REPARATION	1										