

COVER INSTALLATION lower cab  
ABDECKUNG EINBAU unter Fahrerhaus  
RECOUVREMENT INSTALLATION bas cabine

from No / up to No  
WFN5RUDP752029101  
WFN5RUDP752029114

Figure  
Bild 99707771449  
Figure

**TADANO**  
2901-01

