


VALVE
SCHNELLOESEVENTIL
VALVE DESSER RAPIDE

997-084-06729

Figure
Bild
Figure

8406729

1627-05



Item Pos. Réf	Part No. Teil-Nr. Pièce No	Designation Benennung Désignation	all alle tous	Qty/assy Stck/Variante Pièce/ensemble								Figure Bild Figure	
				A	B	C	D	E	F	G	H		
1	997-084-06729	VALVE ASSY SCHNELLOESEVENTIL KPL VALVE DESSER RAPIDE CPL	0										
3	997-084-61448	SEALING RING DICHRING ANNEAU D ETANCHEITE	1										
4	997-014-09025	DIAPHRAGM MEMBRANE MEMBRANE	1										
8	997-007-66480	FILLISTER HEAD SCREW M6X16 LINSCHRAUBE VIS A TETE BOMBEE	4										
9	997-084-74960	REPAIR KIT ASSY REPARATURSATZ KPL LOT DE REPARATION CPL	1										